

**Release Notes
PAWS WRTS
Version 01.34.09
22 November 2006**

- 1.1 Critical Items
- 1.2 Known Limitations
- 1.3 Enhancements
- 1.4 Problem Reports

PR06124 Socket Communication between Graphics Viewer & RTS displays errors

The problem was caused by an overwhelming output from the ATLAS - RTS to the Graphics Viewer (Java) application. The RTS did not use any control in writing to the socket, thus causing the problem. This has been resolved by controlling the data transfer to the write buffer, from the RTS side, by using the socket overlapped communication protocol.